


DS2700

3-BAR LED LIGHT KIT


INSTALLATION INSTRUCTIONS



STEP #1. Turn Power Off to Vending Machine

STEP #2. Remove the original fluorescent fixture

STEP #3. Cut the plug off the end of the fixture. This will be used later to connect power to the power supply.



STEP #4. Crimp the female spade terminals supplied in the kit to the plug that was cut off in Step #2 then connect it to the input of the power supply.



STEP #5. Mount the power supply using the existing trim screw (If there is no screw there due to different header panels use the velcro in the kit). Secondly, plug the power supply into the existing power cable.



STEP #6. Install the mounting clips using the existing trim screws along side the glass and the top trim.



2062 East 70th Street
Cleveland, Ohio 44103
dsvendinginc.com

ESTABLISHED 1965
Quality Rebuilt Vending Equipment
Sales - Repairs - Reconditioning - Parts
Evaluations - Appraisals - Service Calls

(216) 361-0332 Toll Free (800) 445-8363 24 Hour FAX (800) 275-8583



2062 East 70th Street
Cleveland, Ohio 44103
dsvendinginc.com

ESTABLISHED 1965
Quality Rebuilt Vending Equipment
Sales - Repairs - Reconditioning - Parts
Evaluations - Appraisals - Service Calls

(216) 361-0332 Toll Free (800) 445-8363 24 Hour FAX (800) 275-8583

STEP #7. Slip the supplied zip ties through the holes of the clips. You can now snap the LED strips into the clips and secure them with the zip ties.



STEP #8. Plug all of the strips into each other, and using the supplied wire clamps and zip ties secure the wires



Additional AP Ballast Bypass

All AP Snacks have to have the ballast bypassed. Cut the wires coming out of the ballast and reconnect them as shown in the projects.

