

## **Installation Instructions for MDB/DEX Vend Wizard On AP6000 & AP7000**

The “**Vend Wizard**” conversion kit is designed to eliminate refunds by detecting the delivery of a product from your snack machine.

**Note: This kit has been designed for use with a MEI 7512, VN4510, TRC-6512, or TRC-6510 MDB coin mech. and a MEI VN2502 MDB validator or a MEI VN2501 (110V), VFM3 MicroMech validator. Please refer to appendix A for further information on VN2501 (110V) or a VFM3.**

### Parts Included with 9310VWDM kit:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>
9300MBA	Main Box Assembly	1
9300S	Sensor and Bracket Assembly	1
9300L	Vend Wizard Label	1
9672	Coins/\$1/\$5 Label	1
9308A	Magnet (w/ 2 sided tape)	1
9300RT	Reflective Tape	3
7206	8-32 Hex Nut	1
4601	6” Cable Tie	8
4560	Cable Tie Hold Down	8

**Note: Before proceeding with conversion kit installation. It is recommended that you thoroughly read and understand these instructions, to minimize installation times and confusion. Ensure vending machine, validator and coin mech. are in good working order. After verifying vending machine, validator and coin mech. are in good working order. Turn off and unplug machine, until instructed otherwise.**

